ABSTRACT

Disclosed are methods for extracting excess materials from contact lenses, during which the contact lenses swell above their functional size. The methods include the steps of treating contact lenses with a liquid, preferably a solution that causes the contact lenses to swell to a size larger than their functional size, and treating the contact lenses with a liquid, preferably a solution that causes them to shrink back to their functional size.